

02168985 SALUDA RIVER ABOVE I-26, #5, AT COLUMBIA, SC

Santee Basin
Saluda Subbasin

LOCATION.--Lat 34°01'22", long 81°05'54" referenced to North American Datum of 1927, Richland County, SC, Hydrologic Unit 03050109, on left bank above rock shoal approximately 0.13 mi downstream of I-26 and 7 mi downstream of Lake Murray Dam.

SURFACE-WATER RECORDS

PERIOD OF RECORD.--Annual maximum, November 1969 to July 2011 (discontinued).

GAGE.--Creat-stage gage. Minimum recordable elevation is 164.92 ft above NAVD 1988. Prior to October 1, 1999, at same site at different datum.

**MAXIMUM PEAK DISCHARGE
WATER YEAR OCTOBER 2010 TO SEPTEMBER 2011**

Date	Discharge, in ft³/s	Discharge qualification code	Gage height, in ft	Gage height qualification code
Nov 28, 2010	---	B	165.23	4

Discharge qualification code:

B - Month or day of occurrence is unknown or not exact

Gage height qualification code:

4 - Gage height below minimum recordable elevation