

Water-Data Report 2008

355856078492945 RAINGAGE AT LITTLE LICK CREEK AT NORTH CAROLINA HIGHWAY 98 AT OAK GROVE, NC

Neuse Basin Upper Neuse Subbasin

LOCATION.--Lat 35°58'56.3", long 78°49'29.4" referenced to North American Datum of 1983, Durham County, NC, Hydrologic Unit 03020201, on left bank on south side of North Carolina Highway 98 at Oak Grove.

CLIMATOLOGICAL RECORDS

COOPERATION.--Gage is operated in cooperation with the Stormwater Services Division, City of Durham, NC.

PERIOD OF RECORD.--August 2008 to September 2008.

INSTRUMENTATION.--Tipping-bucket raingage. Satellite telemetry at station.

Water-Data Report 2008

355856078492945 RAINGAGE AT LITTLE LICK CREEK AT NORTH CAROLINA HIGHWAY 98 AT OAK GROVE, NC-Continued

Day	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep
1												0.00
2												0.00
3												0.00
4												0.00
5												0.28
6												4.86
7												0.00
8											0.00	0.00
9											0.00	0.00
10											1.03	0.38
11											0.00	0.00
12											0.00	0.00
13											0.11	0.00
14											0.00	0.00
15											0.10	0.00
16											0.00	1.15
17											0.09	0.00
18											0.00	0.00
19											0.00	0.00
20											0.49	0.00
21											0.00	0.00
22											0.00	0.00
23											0.00	0.00
23											0.00	0.00
24											0.00	0.00
											0.00	0.08
26											0.17	3.14
27											4.44	0.19
28											1.78	0.00
29											0.00	0.00
30											0.00	0.03
31											0.32	
Total												10.11

PRECIPITATION, TOTAL, INCHES WATER YEAR OCTOBER 2007 TO SEPTEMBER 2008 DAILY SUM VALUES

355856078492945 RAINGAGE AT LITTLE LICK CREEK AT NORTH CAROLINA HIGHWAY 98 AT OAK GROVE, NC—Continued

