



Water-Data Report 2009

06342266 NORTH BRANCH OTTER CRK AB HARMON LK NR MANDAN, ND

Lake Oahe Basin
Painted Woods-Square Butte Subbasin

LOCATION.--Lat 46°55'51", long 101°00'01" referenced to North American Datum of 1983, in SE ¼ NW ¼ sec.23, T.140 N., R.82 W., Morton County, ND, Hydrologic Unit 10130101, at bridge on County Road 13 miles northwest of Mandan.

DRAINAGE AREA.--Not determined.

SURFACE-WATER RECORDS

PERIOD OF RECORD.--March to April 2009.

GAGE.--Miscellaneous discharge measurements only.

**DISCHARGE MEASUREMENTS
WATER YEAR OCTOBER 2008 TO SEPTEMBER 2009**

Date	Discharge, in ft³/s
Mar 16, 2009	0.000
Mar 19, 2009	0.000
Mar 20, 2009	0.000
Mar 22, 2009	209
Apr 9, 2009	59.8
Apr 11, 2009	77.2
Apr 22, 2009	3.35
Apr 27, 2009	1.83