

**03105940 LITTLE CONNOQUENESSING CREEK AT HARMONY, PA**

Upper Ohio-Beaver Basin  
Connoquenessing Subbasin

LOCATION.--Lat 40°48'37", long 80°06'49" referenced to North American Datum of 1927, Butler County, PA, Hydrologic Unit 05030105, on right bank along Nickle Street and at pumping station for Harmony Borough Water Authority, 0.85 mi northeast of Harmony Borough and 1.3 mi above mouth.

DRAINAGE AREA.--63.8 mi<sup>2</sup>.

**SURFACE-WATER RECORDS**

PERIOD OF RECORD.--1996 to current year.

GAGE.--Non-recording gage. Datum of gage is 910 ft above National Geodetic Vertical Datum of 1929, from topographic map.

COOPERATION.--Station established and maintained by the U.S. Geological Survey in cooperation with the Harmony Water Authority.

**DISCHARGE MEASUREMENTS  
WATER YEAR OCTOBER 2012 TO SEPTEMBER 2013**

<b>Date</b>	<b>Discharge, in ft<sup>3</sup>/s</b>
Mar 27, 2013	168
Apr 30, 2013	87.5
May 21, 2013	20.5